## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.





FIG. 1

02/25/04

A METHOD FOR CORRECTING A MASK... Kahng et al. Greer, Burns & Crain, Ltd. (B. Joe Kim) Ref. No. 0321.67421 Sheet 2 of 3 (312) 360-0080





F1G. 2(6)

A METHOD FOR CORRECTING A MASK... Kahng et al. Greer, Burns & Crain, Ltd. (B. Joe Kim) Ref. No. 0321.67421 Sheet 3 of 3 (312) 360-0080

GATE SIZING PROBLEM	MINIMUM COST OF CORRECTION PROBLEM
AREA	COST OF CORRECTION
NOMINAL DELAY	DELAY μ+ksigma
CYCLE TIME	SELLING POINT DELAY
DIE AREA	TOTAL COST OF RET

FIG. 3